

REV A	APPLICATION			REVISIONS		
	NEXT ASSEMBLY	FINAL ASSEMBLY	REV	DESCRIPTION	DATE	APPROVED
SH 1		RT-138F	A	INITIAL RELEASE		
				PER DCN W1185	8/17/00	UWallace
DWG. NO. 150-040811						

THIS COVER SHEET IS FOR WULFSBERG ELECTRONICS DIVISION INTERNAL USE. IT IS NOT TO BE PUBLISHED WITH THE DOCUMENT IT DESCRIBES

THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF WULFSBERG ELECTRONICS DIVISION, A CHELTON GROUP COMPANY. NEITHER RECEIPT NOR POSSESSION THEREOF CONFERS ANY RIGHT TO REPRODUCE, OR USE, OR DISCLOSE, IN WHOLE OR IN PART, ANY SUCH INFORMATION WITHOUT WRITTEN AUTHORIZATION FROM WULFSBERG ELECTRONICS DIVISION.



Wulfsberg Electronics Division
A Chelton Group Company
 Prescott, AZ 86301 U.S.A.

APPROVALS	DATE	TITLE			
		SERVICE BULLETIN WSB RT-138F-2			
DRAWN		INCORRECT MOD MARKING			
<i>UWallace</i>	8/17/00	SIZE	CAGE CODE	DWG. NO.	REV
CHECKED					
<i>UWallace</i>	3-21-01	A	1B7G3	150-040811	A
ENGINEER		SCALE NONE			SHEET 1 OF 3
<i>UWallace</i>	8/17/00				



Wulfsberg Electronics Division

A Chelton Group Company

6400 Wilkinson Drive • Prescott, AZ 86301 • U.S.A
Telephone: (520) 708-1550 • FAX: (520) 541-7627

SERVICE BULLETIN

EQUIPMENT: RT-138F

DATE: August 17, 2000

BULLETIN NUMBER: WSB RT-138F-2

APPLICABILITY

This Service Bulletin applies to RT-138F Flexcomm I Transceivers, P/N 400-014525-XX with serial number 1652 thru 1734.

REASON

The units noted above were shipped with an incorrect mod marking.

EFFECTIVITY

Modifications described in this document are to be performed at the time of next regularly scheduled maintenance.

REFERENCES

RT-138F Configuration Index Document, P/N 149-140210.

DESCRIPTION

Does not affect the performance of the unit, the Mod Label was incorrectly marked at the factory.

COMPLIANCE

As required by customer.

APPROVAL

This modification does not affect the original approval.

WARRANTY INFORMATION

Units still in the warranty period may be returned for installation of this modification under the terms of the warranty agreement. Units should be sent to:

Wulfsberg Electronics Division
Attention: Repair and Overhaul Department
6400 Wilkinson Drive
Prescott, AZ 86301

MODIFICATION PROCEDURE

1. Reference the Configuration Index Document (P/N 149-140210) to determine the correct Mod level as per the unit flavor. Use a black permanent marker and mark the label with the correct Mod.